







CARFAX® Vehicle History Report™






An independent company established in 1986





















<p>Vehicle Information: 2012 JEEP GRAND CHEROKEE LIMITED VIN: 1C4RJFBT8CC166316 4 DOOR WAGON/SPORT UTILITY 5.7L V8 SFI OHV 16V GASOLINE 4 WHEEL DRIVE</p>	     	<p>Branded Title: Salvage</p> <p>3 Previous owners</p> <p>At least 1 open recall</p> <p>4 Service history records</p> <p>Personal vehicle</p> <p>84,227 Last reported odometer reading</p>
---	--	--

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 11/24/16 at 8:59:47 AM (EST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

 Ownership History	 Owner 1	 Owner 2	 Owner 3
The number of owners is estimated			
Year purchased	2011	2014	2015
Type of owner	Personal	Personal	Personal
Estimated length of ownership	2 years	1 yr. 7 mo.	1 yr. 1 mo.
Owned in the following states/provinces	Michigan, Alabama	Florida	Iowa
Estimated miles driven per year	23,320/yr	22,926/yr	---
Last reported odometer reading	47,218	84,227	---

 Title History	 Owner 1	 Owner 2	 Owner 3
<p>Salvage Junk Rebuilt Fire Flood Hail Lemon </p> <p>Not Actual Mileage Exceeds Mechanical Limits</p>	No Problem	Alert! Problem Found	Alert! Problem Found
	No Problem	No Problem	No Problem
Alert! Severe problems were reported by a state Department of Motor Vehicles (DMV).			

 Additional History	 Owner 1	 Owner 2	 Owner 3
Not all accidents / issues are reported to CARFAX			
<p>Total Loss Total loss reported on 06/12/2015.</p>	 No Issues Reported	 Total Loss Reported	No New Issues Reported
<p>Structural Damage No structural damage reported to CARFAX.</p>	 No Issues Reported	 No Issues Reported	 No Issues Reported
<p>Airbag Deployment No airbag deployment reported to CARFAX.</p>	 No Issues Reported	 No Issues Reported	 No Issues Reported
<p>Odometer Check No indication of an odometer rollback.</p>	 No Issues Indicated	 No Issues Indicated	 No Issues Indicated
<p>Accident / Damage DMV title problems reported. Accidents reported on: 06/10/2013 and 06/12/2015.</p>	 Accident Reported	 Severe Damage	 Severe Damage

Manufacturer Recall

At least 1 manufacturer recall requires repair.

No Recalls
Reported**Recall
Reported****Recall
Reported****Detailed History**

Glossary

Owner 1

Purchased: 2011
 Type: Personal
 Where: Michigan,
 Alabama
 Est. miles/year: 23,320/yr
 Est. length owned: 12/20/11 -
 12/28/13
 (2 years)

Date:	Mileage:	Source:	Comments:
12/20/2011	16	Michigan Motor Vehicle Dept. Lanse, MI Title #380Z3540054	Title or registration issued First owner reported Titled or registered as personal vehicle
12/21/2011	34,000	Alabama Motor Vehicle Dept.	Vehicle purchase reported
09/06/2012		Michigan Motor Vehicle Dept. Lanse, MI	Registration issued or renewed
06/10/2013		Alabama Damage Report	Accident reported Vehicle involved in a rear-end collision Involving rear impact with another motor vehicle Damage reported to: Rear Undercarriage Major damage reported Vehicle disabled Airbags did not deploy
07/09/2013		Alabama Motor Vehicle Dept. Headland, AL Title #47458155	Title issued or updated Loan or lien reported Registration updated when owner moved the vehicle to a new location Vehicle color noted as White
12/28/2013	47,217	Sam Taylor Buick Cadillac, Inc. Fort Walton Beach, FL 850-244-5165 samtaylor.com	Vehicle offered for sale
12/31/2013		Sam Taylor Buick Cadillac, Inc. Fort Walton Beach, FL 850-244-5165 samtaylor.com	Maintenance inspection completed Air filter replaced Nitrogen fill tires Oil and filter changed Tire condition and pressure checked Washed/detailed Wiper(s) replaced
01/30/2014	47,218	Sam Taylor Buick Cadillac, Inc. Fort Walton Beach, FL 850-244-5165 samtaylor.com	Four tires balanced Four tires mounted Nitrogen fill tires Tire condition and pressure checked

Owner 2

Purchased: 2014
 Type: Personal
 Where: Florida
 Est. miles/year: 22,926/yr
 Est. length owned: 2/10/14 -
 9/18/15
 (1 yr. 7 mo.)

Date:	Mileage:	Source:	Comments:
02/10/2014	47,482	Florida Motor Vehicle Dept. Gulf Breeze, FL Title #0114145130	Vehicle purchase reported Title issued or updated Registration issued or renewed New owner reported Titled or registered as personal vehicle Loan or lien reported Vehicle color noted as White
02/21/2014		Florida Motor Vehicle Dept. Gulf Breeze, FL Title #0114250995	Title issued or updated Titled or registered as personal vehicle Loan or lien reported Vehicle color noted as White
03/27/2014	51,730	Lee Chrysler Dodge Fort Walton Beach, FL 850-244-7611 leeautomotive.com	Maintenance inspection completed

04/11/2014 52,319 Lee Chrysler Dodge Maintenance inspection completed
Fort Walton Beach, FL Engine/powertrain computer/module checked
850-244-7611
leeautomotive.com

05/16/2014 FCA US LLC Manufacturer Safety recall issued
#P14 BRAKE BOOSTER

[Click here](#) for a copy of the owner letter for this Recall or call 1- 800-853-1403 if you have any questions or need additional information on this recall.

- [Learn more about this recall](#)

Description: THE BRAKE BOOSTER MAY PREMATURELY CORRODE. IF PERFORATION OF THE BRAKE BOOSTER SHELL (DUE TO CORROSION) OCCURS, THE BRAKE BOOSTER MAY INGEST WATER DURING VEHICLE OPERATION IN WET WEATHER CONDITIONS. A BRAKE BOOSTER THAT HAS EXPERIENCED WATER INGESTION MAY HAVE THE BRAKE FUNCTION COMPROMISED IF THE WATER INSIDE THE BRAKE BOOSTER FREEZES. THE DRIVER MAY BE REQUIRED TO APPLY ADDITIONAL APPLICATION FORCE TO APPLY THE BRAKES DURING SUB FREEZING DRIVING CONDITIONS.

AN UNEXPECTED ADDITIONAL BRAKE PEDAL APPLICATION FORCE REQUIREMENT COULD SLOW THE DRIVERS BRAKE APPLICATION REACTION TIME AND CAUSE A CRASH WITHOUT WARNING.

Remedy: ALL INVOLVED VEHICLES MUST HAVE THE BRAKE BOOSTER INSPECTED FOR CORROSION. BRAKE BOOSTERS FOUND WITH EXCESSIVE CORROSION WILL BE REPLACED. ALL BOOSTERS WILL BE EQUIPPED WITH A SHIELD TO PROTECT THE BRAKE BOOSTER CRIMP JOINTS FROM WATER EXPOSURE.

05/16/2014 FCA US LLC Manufacturer Safety recall issued
NHTSA #14V-154
#P14 BRAKE BOOSTER
Status: Remedy available

[Click here](#) for a copy of the owner letter for this Recall or call 1- 800-853-1403 if you have any questions or need additional information on this recall.

- [Learn more about this recall](#)

Description: THE BRAKE BOOSTER MAY PREMATURELY CORRODE. IF PERFORATION OF THE BRAKE BOOSTER SHELL (DUE TO CORROSION) OCCURS, THE BRAKE BOOSTER MAY INGEST WATER DURING VEHICLE OPERATION IN WET WEATHER CONDITIONS. A BRAKE BOOSTER THAT HAS EXPERIENCED WATER INGESTION MAY HAVE THE BRAKE FUNCTION COMPROMISED IF THE WATER INSIDE THE BRAKE BOOSTER FREEZES. THE DRIVER MAY BE REQUIRED TO APPLY ADDITIONAL APPLICATION FORCE TO APPLY THE BRAKES DURING SUB FREEZING DRIVING CONDITIONS.

AN UNEXPECTED ADDITIONAL BRAKE PEDAL APPLICATION FORCE REQUIREMENT COULD SLOW THE DRIVERS BRAKE APPLICATION REACTION TIME AND CAUSE A CRASH WITHOUT WARNING.

Remedy: ALL INVOLVED VEHICLES MUST HAVE THE BRAKE BOOSTER INSPECTED FOR CORROSION. BRAKE BOOSTERS FOUND WITH EXCESSIVE CORROSION WILL BE REPLACED. ALL BOOSTERS WILL BE EQUIPPED WITH A SHIELD TO PROTECT THE BRAKE BOOSTER CRIMP JOINTS FROM WATER EXPOSURE.

04/10/2015 FCA US LLC Manufacturer Safety recall issued
#R09 FUEL PUMP RELAY

[Click here](#) for a copy of the owner letter for this Recall or call 1- 800-853-1403 if you have any questions or need additional information on this recall.

[- Learn more about this recall](#)

Description: THE TOTALLY INTEGRATED POWER MODULE (TIPM) CONTAINS AN INTERNAL FUEL PUMP RELAY THAT COULD OPERATE INTERMITTENTLY OR FAIL WITHOUT WARNING.

AN INTERMITTENT OR FAILED FUEL PUMP RELAY COULD CAUSE THE ENGINE TO STALL WHILE DRIVING AND CAUSE A CRASH WITHOUT WARNING.

Remedy: THE TIPM INTERNAL FUEL PUMP RELAY MUST BE DISABLED AND AN EXTERNAL FUEL PUMP RELAY MUST BE INSTALLED.

04/10/2015	FCA US LLC	Manufacturer Safety recall issued NHTSA #15V-115 #R09 FUEL PUMP RELAY Status: Remedy available
<p>Click here for a copy of the owner letter for this Recall or call 1- 800-853-1403 if you have any questions or need additional information on this recall.</p>		

[- Learn more about this recall](#)

Description: THE TOTALLY INTEGRATED POWER MODULE (TIPM) CONTAINS AN INTERNAL FUEL PUMP RELAY THAT COULD OPERATE INTERMITTENTLY OR FAIL WITHOUT WARNING.

AN INTERMITTENT OR FAILED FUEL PUMP RELAY COULD CAUSE THE ENGINE TO STALL WHILE DRIVING AND CAUSE A CRASH WITHOUT WARNING.

Remedy: THE TIPM INTERNAL FUEL PUMP RELAY MUST BE DISABLED AND AN EXTERNAL FUEL PUMP RELAY MUST BE INSTALLED.

06/12/2015	Alabama Damage Report	Accident reported Vehicle involved in a rear-end collision Involving front impact with another motor vehicle Damage reported to: Front Major damage reported Vehicle disabled
06/12/2015	Alabama Damage Report	TOTAL LOSS VEHICLE Vehicle declared a total loss by an insurance company Collision damage reported
09/18/2015	84,227 Florida Motor Vehicle Dept.	Vehicle purchase reported
09/25/2015	Florida Motor Vehicle Dept.	Title or registration issued to insurance company
09/25/2015	Florida Motor Vehicle Dept. San Antonio, TX Title #0114250995	SALVAGE TITLE/CERTIFICATE ISSUED Vehicle color noted as White

Owner 3

Purchased: 2015
Type: Personal
Where: Iowa
Est. length owned: 10/9/15 - present (1 yr. 1 mo.)

Date:	Mileage:	Source:	Comments:
10/09/2015		Iowa Motor Vehicle Dept. Des Moines, IA Title #77SC10886	New owner reported SALVAGE TITLE/CERTIFICATE ISSUED Vehicle color noted as White
11/15/2015		Vehicle Exporter	Vehicle exported from Newark, NJ and imported to Gdynia, Poland
02/11/2016		FCA US LLC	Manufacturer Safety recall issued #R71 SUN VISOR WIRING
			Click here for a copy of the owner letter for this

Recall or call 1- 800-853-1403 if you have any questions or need additional information on this recall.

- [Learn more about this recall](#)

Description: THE SUN VISORS ON YOUR VEHICLE MAY EXPERIENCE A HIGH RESISTANCE SHORT AT THE SUN VISOR VANITY LAMP WIRING AFTER A SERVICE REPAIR TO THE SUN VISOR, HEADLINER OR WHILE GAINING ACCESS ABOVE THE HEADLINER.

THIS MAY RESULT IN AN INOPERATIVE VANITY LAMP AND/OR AN ELECTRICAL FIRE.

Remedy: THE SUN VISOR WIRING MUST BE INSPECTED ON ALL INVOLVED VEHICLES THAT MAY HAVE HAD AN IMPROPER SERVICE PROCEDURE. ANY DAMAGED SUN VISOR VANITY LAMP WIRING WILL BE REPAIRED. ALSO, THE SUN VISORS WILL BE REPLACED, THE SHEET METAL WILL BE MODIFIED AND WIRE GUIDES WILL BE INSTALLED TO REROUTE SUN VISOR VANITY LAMP WIRING TO PREVENT WIRING DAMAGE.

02/11/2016

FCA US LLC

Manufacturer Safety recall issued
NHTSA #15V-879
#R71 SUN VISOR WIRING
Status: Remedy available

[Click here](#) for a copy of the owner letter for this Recall or call 1- 800-853-1403 if you have any questions or need additional information on this recall.

- [Learn more about this recall](#)

Description: THE SUN VISORS ON YOUR VEHICLE MAY EXPERIENCE A HIGH RESISTANCE SHORT AT THE SUN VISOR VANITY LAMP WIRING AFTER A SERVICE REPAIR TO THE SUN VISOR, HEADLINER OR WHILE GAINING ACCESS ABOVE THE HEADLINER.

THIS MAY RESULT IN AN INOPERATIVE VANITY LAMP AND/OR AN ELECTRICAL FIRE.

Remedy: THE SUN VISOR WIRING MUST BE INSPECTED ON ALL INVOLVED VEHICLES THAT MAY HAVE HAD AN IMPROPER SERVICE PROCEDURE. ANY DAMAGED SUN VISOR VANITY LAMP WIRING WILL BE REPAIRED. ALSO, THE SUN VISORS WILL BE REPLACED, THE SHEET METAL WILL BE MODIFIED AND WIRE GUIDES WILL BE INSTALLED TO REROUTE SUN VISOR VANITY LAMP WIRING TO PREVENT WIRING DAMAGE.

Have Questions? Consumers, please visit our Help Center at www.carfax.eu



Glossary

[View Full Glossary](#)

Accident / Damage Indicator

CARFAX receives information about accidents in all 50 states, the District of Columbia and Canada. Different information in a vehicle's history can indicate an accident or damage, such as: salvage auction, fire damage, police-reported accident, crash test vehicle, damage disclosure, collision repair facility and automotive recycler records. Not every accident or damage event is reported and not all reported are provided to CARFAX. Details about the accident or damage event when reported to CARFAX (e.g. severity, impact location, airbag deployment) are included on the Vehicle History Report. CARFAX recommends you obtain a vehicle inspection from your dealer or an independent mechanic.

- According to the National Safety Council, Injury Facts, 2015 edition, 8% of the 254 million registered vehicles in the U.S. were involved in an accident in 2013. Over 74% of these were considered minor or moderate.
- CARFAX depends on many sources for its accident / damage data. CARFAX can only report what is in our database on 11/24/16 at 8:59:47 AM (EST). New data will result in a change to this report.

Alabama Damage Reports:

- Provide an estimate of the extent of damage in its accident reports for the following:

- MAJOR: The accident damage was major and may affect the operation of the vehicle.
 - MINOR: The accident damage does not affect the operation of the vehicle and should not compromise vehicle safety.
 - NO DAMAGE: The vehicle was not damaged.
 - DISABLED: The vehicle cannot be driven from the accident scene due to severe damage or an injury.
 - FUNCTIONAL: The vehicle could be driven from the accident location.
-
- Are required if the estimated damage exceeds \$500

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform owners of car defects that have come to the manufacturer's attention. Recalls also suggest improvements that can be made to improve the safety of a particular vehicle. Most manufacturer recalls can be repaired at no cost to you.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Salvage Title

A Salvage Title is issued on a vehicle damaged to the extent that the cost of repairing the vehicle exceeds approximately 75% of its pre-damage value. This damage threshold may vary by state. Some states treat Junk titles the same as Salvage but the majority use this title to indicate that a vehicle is not road worthy and cannot be titled again in that state. The following eleven states also use Salvage titles to identify stolen vehicles - AZ, FL, GA, IL, MD, MN, NJ, NM, NY, OK and OR.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Total Loss Vehicle

An insurance or fleet company declares a vehicle a total loss when a claim exceeds approximately 75% of its pre-damage value or if the vehicle is stolen and not recovered. This damage threshold varies by company. These companies typically take possession and obtain the title. Not all total loss vehicles result in a DMV-reported branded title. This may occur when an insurance company's definition of a total loss is different than the state DMV's definition for a branded title or when the owner of the vehicle is a self-insured company, like a fleet or rental company.

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. CARFAX®

© 2016 CARFAX Europe GmbH, a unit of IHS Inc. All rights reserved.

Covered by United States Patent Nos. 7,113,853; 7,778,841; 7,596,512, 8,600,823; 8,595,079; 8,606,648; 7,505,838.

11/24/16 8:59:47 AM (EST)